

# KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT:

Fuel Spill

DATE OCCURRED 10-14-93

TIME OCCURRED 7:15AM

DATE REPORTED 10-14-93

TIME REPORTED 7:30 Am

LOCATION(S) OF OCCURRENCE:

Gate #6

REPORTED BY:

On View

PHONE NO(S):

SUMMARY:

A fuel spill of about 5 gallons occurred under UPS 575 #405UP parked at gate 6. Officer VanderBie responded to the area in FD#2. Two Galvin's employees had cleaned up the spill with absorbant before officer VanderBie arrived.

OFFICERS:

*L. D. Reed*

ACTION:

LEB	JE	PP	JW
JEB	TKL	LGP	
BLC	PEM	GCS	
SHD	GO	JRV	